This set of photographs has been annotated to provide an initial consideration of the repairs to be carried out to the former swing bridge foundations.




General view of the offside wall




Northeast end, section 1



Section 2



Section 3



Section 4




Section 5




Southwest end, section 6




General view of the towpath wall




Northeast end, Section 1



Section 2



Section 3



Section 5



Southwest end, section 6