## **WENDOVER ARM TRUST**

### RISK ASSESSMENTS

# RISK CATEGORY :- GENERIC

WATRA 2

Reviewed

Task / Activity	Hazardous Events and Potential Causes	Group / Individual At Risk	Likelihood	Severity	Risk	Controls and Precautions Implemented to Reduce Risk	Risk Assessment with Controls in Place	Date Assessed	Date Re- assessed
General activities associated with restoration.	General risk associated with a construction site.  i.e. Knocks Cuts Falls Strains and sprains Risk to eyes Risk to hearing Risk from hazardous materials and substances etc.	WAT restoration team	Likely	Major injury Fatality	High	All members of the restoration team made fully aware of the inherent dangers associated with working on a potentially dangerous site.  All restoration volunteers are issued with a "Restoration" handbook. Refer to section 2 of the handbook for further information.  Hard hats and high visibility jackets are issued and the wearing of them is mandatory.  Eye protection and ear defenders are always available and must be used whenever necessary. Recommendation is given regarding the wearing of other suitable clothing. i.e. Gloves, Suitable footwear etc.	Low	18/09/2005	
	Working in muddy and slippery conditions	All people entering site	Likely	Serious injury	High	Due to the nature of the activity it is unavoidable that at times conditions will be muddy and slippery.  All people entering the site must be made aware of this fact and warned to take extra care.  Where possible extra precaution will be taken to reduce the risk i.e. Specific "safe" walkways possibly with pallets or planking laid down.	Low	15/10/2007	

### RISK ASSESSMENTS

# RISK CATEGORY :- GENERIC

WATRA 2

Task / Activity	Hazardous Events and Potential Causes	Group / Individual At Risk	Likelihood	Severity	Risk	Controls and Precautions Implemented to Reduce Risk	Risk Assessment with Controls in Place	Date Assessed	Date Re- assessed
General activities associated with restoration.	Access to and Egress from site	All people entering site	Likely	Major injury	High	A safe means of Access to and Egress from the work area must be provided.  i.e A dedicated route    Steps cut into bank    Provision of steps or ladders etc.  All persons entering the site to be warned of the possible dangers and directed to safe Access and Egress point.  All restoration volunteers are issued with a "Restoration" handbook.  Refer to section 2 of the handbook for further information.	Low	15/10/2007	

Assessed By

RAO

RAO

RAO

Page 2

Assessed By

RAO