

Task / Activity	Hazardous Events and Potential Causes	Group / Individual At Risk	Likelihood	Severity	Risk	Controls and Precautions Implemented to Reduce Risk	Risk Assessment with Controls in Place	Date Assessed	Date Re-assessed	Assessed By
Use of Hand Tools	Striking, cutting, crushing, splinters, ejection of materials	WAT restoration team	Likely	Major injury	High	Hand tools must only be used by competent and capable people. Use appropriate tools for the job. All appropriate PPE must be worn. Inspect tools for damage before use. All tools must be maintained in good condition. When used near electrical source or supply make sure supply is isolated. Care must be taken to avoid any heavy lifting / manual handling hazards (refer to WATRA 3).	Low	24/09/2005	22/06/2020	RAO Re-assessed by M Wright
	Hazardous materials, inhalation of dust, swallowing, eye contact etc.	WAT restoration team	Likely	Major injury, fatality	High	Where appropriate a COSHH assessment of material to be worked on should be carried out and any identified precautions followed. All appropriate PPE must be worn.	Low	18/09/2005	22/06/2020	RAO Re-assessed by M Wright